

Priority Trending Report

Item	DESCRIPTION	May	July	Sept.	Nov.	Jan.	March
#		2020	2020	2020	2020	2021	2021
1	ZLC Flexo Printing Press						N/C
2	Koppers Printing Press NV-35	2	2				
3	Simon Printing Press						
4	Koppers Printing Press NSL-100		2	2			2
5	Bobst Die Cutter Motor						
6	"C" Flute Pressure Fan	4	4	3	4	3	3
7	"C" Flute Main Drive Motor						
8	"C" Flute Conveyor Drive Motor		,				
9	"B" Flute Main Drive Motor	3	N/C	3	N/C		2
10	"B" Flute Bridge Conveyor Drive	3	N/C		N/C		
11	Double Facer Main Drive Motor						
12	Top Knife Main Drive Cooling Fan						
13	Top Knife Main Drive, Gearbox & Rolls						
14	Starch Mixer			1			
15	Baler Pump						2
16	Upper Trim Fan	2	3	3	3	2	2
17	Lower Trim Fan	3	3	3	3	7	4
18	ZLC Scrap Fan (if lift available)	5	5	4	3	4	5
19	NV35 & Simon Scrap Fan	4	4	4	4	4	3
20	East Scrap Fan	4	4	5	3	3	4
21	Bobst Scrap Fan	5	5	7			3
22	113 Printing Press Motor (4 Colour)			2			2
23	B - Flute Gearbox		N/C		N/C		
24	Knife Upper Cylinder						
25	Knife Lower Cylinder						
26	Slitter-Scorer Lower Gearbox 3/4					3	1.
27	Slitter-Scorer Upper Gearbox 1/2		4		2	2	
28	Double Backer - Head Pulley Gearbox		2	2	2	3	2
29	Double Backer - Tail Pulley Roll						
30	Glue Machine - Upper Rolls						
31	Glue Machine - Lower Rolls						
32	#1 NSL Vacuum Fan		1		2	2	3
33	#2 NSL Vacuum Fan					1	2
34	Automatron Vacuum Pump		, p	4	4		
35	Automatron Turbine		N/C		N/C		3
36	McKinley Die Cutter Motor						

	4.00	4.00	4.40	0.04	0.00	4 4 4
Plant Average Priority per machine checked	1.33	1.06	1.16	0.91	0.89	1.14

Priority: "0" = No Action Required; "1" Low Priority to "5" High Priority; "7" = Don't Run Lightly shaded boxes are "Not Checked" and not included in totals. i.e. No shading and no number means the machine was checked and no action is required. Solid shading means the machine was not on the route at the time of the inspection.

